

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

1477  
NW  
> 1  
1.867 mi.  
9858 ft.

MH 56526  
8898 20TH AVE  
BROOKLYN, NY

NY Spills S106010810  
N/A

Relative:  
Higher

Actual:  
0 ft.

SPILLS:

Name: MH 56526  
Address: 8898 20TH AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0210518 / 2003-02-26  
Facility ID: 0210518  
Facility Type: ER  
DER Facility ID: 134101  
Site ID: 158705  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2003-01-19  
Investigator: KMFOLEY  
Referred To: Not reported  
Reported to Dept: 2003-01-19  
CID: 396  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0

Date Entered In Computer: 2003-01-19  
Spill Record Last Update: 2003-02-26  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 001

Contact Name: MARK SCHLAGEL

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was FOLEY Con Ed e2mis #146803: 1/19/03 - 0955 C. LUGO - 03594 - ENV. OPS., REPORTS FINDING APPROX 2 QTS OF AN UNKNOWN OIL MIXED WITH APPROX 1 GAL OF WATER IN MH56526. SPILL APPEARS TO BE CONTAINED. NO SEWERS OR WATERWAYS AFFECTED. NO FIRE OR SMOKE INVOLVED. NO INJURIES RELATED TO SPILL. NO PRIVATE PROPERTY AFFECTED. NO MOVEMENT IN THE WATER. NO SEWER CONNECTION. THERE IS AN EARTHEN SUMP. NO LARGE CRACKS IN THE STRUCTURE. NO PARKING 1130 - 1300 MON. TAG # 34802 PLACED IN STRUCTURE. PCB SAMPLE TAKEN. CHAIN OF CUSTODY FORM # CC16330 FILLED OUT AND MARKED 'E' (WITHIN 8 HRS) PRIORITY. CLEANUP PENDING LAB RESULT. From: Sauer, Jocelyne Sent: Sunday, January 19, 2003 2:33 PM Lab Sequence Number: 03-00500-001 Date Approved: 1/19/2003 E2 Incident Number: 146803 Date Received: 1/19/2003 Chain of Custody ID: CC16330 Date Sampled: 1/19/2003 Aroclor 1260 < 1.0 ppm EPA 608/8082 1/20/03-0230HRS D.LICTENSTEIN ENVIR OPS REPORTS CLEANUP COMPLETED . DOUBLE WASHED STRUCTURE USING BIO-GEN 760. CEMENTED SUMP. REMOVED ENVIR TAG # 34802."

Remarks: "2 quarts unk oil in mh. samples tkaen clean up pending. there is an earthen sump in mh ref # 146803."

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID:	158705
Operable Unit ID:	861723
Operable Unit:	01
Material ID:	513902
Material Code:	0064A
Material Name:	unknown material
Case No.:	Not reported
Material FA:	Other
Quantity:	2.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported